





AN OUNCE OF PREVENTION IS WORTH A POUND OF CURE -WINTERIZATION IS THE BEST INSURANCE YOU CAN BUY

HOW WILL YOU PROTECT YOUR RIG SITE FROM

OLD MAN WINTER?

Winter weather can have a major impact on oil field housing operations. Fluids freeze, parts become brittle and electrical circuits become burdened. HB Rentals has applied the best processes and technology to keep essential functions operating as you need them. But Old Man Winter always has a few surprises to throw our way, and when that happens, our experienced Service Technicians are available to quickly correct any issue should they occur.







ISSUE: Sometimes our heat trace is unplugged from the outlet to make room for an engine block heater. Make sure all lines are plugged in.

SOLUTION: If a line was unplugged, plug in and the line should thaw shortly.




ISSUE: Due to extra electrical power demands in the winter, a GFCI may trip and no longer provide power to a heat trace line, pump heater or the pump itself.

SOLUTION: If a GFCI has tripped, push the REST button and power should return to assist in thawing out any lines that froze in the absence of power. If a GFCI continues to trip, please call our service department.



ISSUE: The toilet seems to be backing up and not flushing. This could be a sign that the GFCI has tripped or the lift station outside of the skid house is frozen.





ISSUE: The skid house doesn't seem to be getting warmer.

SOLUTION: Check that all the registers and returns are clear and uncovered. See that the air filter is clean and clear. Check that someone hasn't adjusted the thermostat. If the heating issue persists, please contact your local service department.